

Unica Pro Firmware Release Notes

V1.1.11.2244

General Feature Update (01.02.2023)

Features and fixes

- Log file including serial number
- Blooming shot timeout min value changed from 1.0 to 0.0 bar
- Pressure ramp unit [bar/s] implemented and now shown on UI
- Steamboiler enable with tap for all energy (exempt eco) modes possible
- Two steam timer for upper and lower lever possible with updated UI
- Steam levers only switches if steam boiler temperature is over 100°C
- Portafilter detection updated
- Updated cleaning instructions
- Bugfix of history file export

Known issues in work

- Possible wrong temperature error for steam boiler
-

V1.1.4.2237

First field update release (17.12.2022)

Features and fixes

- Fix of steam boiler fill behavior
- Activated gesture control for all scroll menus
- Implementation of ramp control for pressure profiling
- Copy user parameters into default parameters at recipe export
- Check recipe compatibility while import and open
- Update temperature error handling

Known issues in work

- Portafilter detection sometimes hangs up
 - Export of log files sometimes crash
 - Possible wrong temperature error for steam boiler
-

V1.0.1.2232

Official hotfix release (03.09.2022)

Features and fixes

- Fix of the Recipe naming bug: every fifth recipe had the wrong name in the main screen ("Hot Water" instead of the defined one).

Known issues

- Portafilter detection sometimes hangs up
- Steam boiler shows strange behavior if water tank is empty

V1.0.0.2231

First official release (21.08.2022)